


# Case study of AVGT-02-05



间隔板加工图(热浇道部份)